



| | |
|--------|---|
| GROUP | MODEL |
| BOD | 2023MY Niro PHEV, EV (SG2 PHEV, EV) |
| NUMBER | DATE |
| 316 | May 2023 |

TECHNICAL SERVICE BULLETIN

SUBJECT: **SERVICE ACTION: ICU FUSE LABEL REPLACEMENT (SA530)**

This bulletin provides information to replace the Integrated Central Control Unit (ICU) fuse label on some 2023MY Niro PHEV, EV (SG2 PHEV, EV) vehicles produced from July 11, 2022 through February 3, 2023. The incorrect ICU fuse label on the affected vehicles was installed. Follow the procedure outlined in this publication to replace the ICU fuse label. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.



NOTICE


A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA530.

Repair Procedure:

1. Locate the ICU fuse panel cover (A).



2. Remove orange ICU fuse label.

3. Install new yellow ICU fuse label.

4. Reinstall ICU fuse panel cover.



SUBJECT:

ICU FUSE LABEL REPLACEMENT (SA530)**AFFECTED VEHICLE RANGE:**

| Model | Production Date Range |
|------------------------------|-----------------------------------|
| Niro PHEV, EV (SG2 PHEV, EV) | July 11, 2022 to February 3, 2023 |

REQUIRED PART:

| Part Name | Part Number | Figure | Qty. |
|--------------------|----------------|--|------|
| PHEV Fuse Label | 91990 AT120QQK |  | 1 |
| EV Fuse Label | 91990 A0020QQK |  | |

WARRANTY INFORMATION:**N Code: N99 C Code: C99**

| Claim Type | Causal P/N | Qty. | Repair Description | Labor Op Code | Op Time | Replacement P/N | Qty. |
|------------|----------------|------|--------------------------------------|---------------|------------|---|------|
| V | 84753 AT110CCV | 0 | (SA530) Fuse Label Replacement | 230007R0 | 0.2 M.H | 91990 AT120QQK or 91990 A0020QQK | 1 |

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference **SA530** when accessing the WebDCS system.

